



The following products are NOT eligible for pay-for-support:

Cameras

DCS-2132L
DCS-2330L
DCS-2332L
DCS-2530L
DCS-2630L
DCS-5009L
DCS-5010L
DCS-5020L
DCS-5025L
DCS-5029L
DCS-5030L
DCS-5222L
DCS-6045KT
DCS-800L
DCS-820L
DCS-825L
DCS-850L
DCS-855L
DCS-930L
DCS-931L
DCS-932L
DCS-933L
DCS-934L
DCS-935L
DCS-936L
DCS-940L
DCS-942L
DCS-960L
DCS-8200LH

Routers

COVR-3902
COVR-P2502
DGL-5500
DIR-505
DIR-505L
DIR-506L
DIR-508L
DIR-510L
DIR-600L
DIR-601
DIR-605L
DIR-615
DIR-619-ES
DIR-626L
DIR-636L
DIR-640L
DIR-645
DIR-651
DIR-655
DIR-660
DIR-808L
DIR-810L
DIR-813
DIR-815
DIR-817LW
DIR-818LW
DIR-820L
DIR-826L
DIR-827
DIR-830L
DIR-836L
DIR-842
DIR-850L
DIR-855L
DIR-859
DIR-860L
DIR-866L
DIR-868L
DIR-869
DIR-879
DIR-880L
DIR-885L
DIR-890L
DIR-895L
DSL-2740B