

R15 Firmware Release Notes

Firmware: v1.07

Hardware: A1

Date: November 28th, 2022

Wi-Fi Country code support:

AU, BD, BR, CA, EG, EU, ID, IN, IT, KR, LA, MA, NA, RU, SG, SG1, TH, TW, US

DFS band support:

AU, BR, CA, EG, EU, IN, KR, MA, NA, SG, SG1, TH, TW, US

Problems Resolved:

- Fix Security issue (DNS proxy in Extender/AP mode).
- Fix IoT issue with DWP-1010 in modem mode.
- Fix IPv6 Prefix issue
- Fix slow speed working with specific Android device.
- Change DNS client server (IPv6).

Enhancements:

- Improve Guest Zone in mesh network.
- Improve DFS behavior.
- Improve Auto channel selection (Wi-Fi).
- Improve Mesh stability, connection, topology and client list.
- Improve PPPoEv6.
- Improve Mesh Roaming(11v).

Known issues:

- Need to improve QoS.
 - Need to improve IPv6.
 - VPN service not worked on Android device. (Android OS does not support RSA encryption 2048-bit yet).
-
-

=====END=====