



R15/M15/E15 Firmware Hotfix Release Notes

Firmware: 1.08B02

Hardware: A1

Date: 4/28/2023

Problems Resolved:

3rd party reported Reaver / jjy470742953 at gmail dot com

Fixed a WPS PIN vulnerability

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.